MARKERALE CONTY

Bureau of Land Management Branch of Solid Minerals (U-921) 324 South State Street Salt Lake City, Utah 84111-2303

3530/9239 (UT-921) (UTU-69383)

(UTU-087809-087818)

CERTIFIED MAIL—Return Receipt Requested

Mr. Glenn Wadsworth
Reilly Industries
P.O. Box 580
Wendover, Utah 84083

DEGET VIED M/045/002

APR 1 8 1994

BIV. OF OIL, GAS & MINING

Re: Trespass Acreage and Reclamation Plan Review

Dear Mr. Wadsworth:

As per our meeting held on March 25, 1994, at the Bureau of Land Managements' (BLM) Salt Lake District Office, the BLM agreed to provide the following information:

1. Amount of acreage (½ mile influence) that should be used for mitigation of trespass on the Wendover Bombing Range. Enclosure 1 is a map of the area. The legal description is as follows:

T. 2 S., R. 19 W., SLM

Section 5, W½NE¼, NW¼SE¼, NE¼SW¼, S½SW¼, SW¼NW¼;

Section 8, W1/2;

Section 20, W1/2;

Section 17, SW¼, E½NW¼, E½W½NW¼.

Total 1,220 acres, more or less.

2. Review of the Reilly (Kaiser) Reclamation Plan (Notice of Intent to Commence Mining Operations) filed with the State of Utah, Division of Oil, Gas, and Mining.

The BLM has reviewed this document dated February 6, 1976, and has concluded that there is no plan for backfilling the ditches and excavations on the Federal leases on which Reilly presently operates. Section 5 of the readjusted lease, effective January 1, 1984, requires the lessee "... to fill any pits, ditches and other excavations, remove or cover all debris, and so far as reasonably possible, restore the surface of the leased land and access roads to their former condition, including the removal of structures as and if required."

The Bureau of Land Management requires a mine plan update for ditch/dike closure to reflect the terms and conditions of the lease. We are prepared to discuss this requirement at the meeting we all agreed to schedule for mid-May.

Sincerely,

/s/ Douglas M. Koza

Douglas M. Koza Deputy State Director Mineral Resources

**Enclosure** 

bcc: District Manager, Salt Lake
UDOGM, Attn: Wayne Hedberg
UT-942
Solid File
Solid Chron